



中山環境林歩道整備業務

(1工区)

① A3付近

整備完了状況 (R7. 6. 5時点)



② A6付近

整備完了状況 (R7. 6. 5時点)



③ A13付近

整備完了状況 (R7. 6. 5時点)



中山環境林歩道整備業務

(1工区)

④ A18付近

整備完了状況 (R7. 6. 5時点)



⑤ A20付近

整備完了状況 (R7. 6. 5時点)



⑥ B6付近

整備完了状況 (R7. 6. 5時点)